



SIERRA ENVIRONMENTAL GROUP, INC.

December 8, 2015

Mr. Dennis Zimmer
City of Dayton
Department of Building Services/Division of Housing Inspection
P.O. Box 22
371 West 2nd Street, Room 324
Dayton, OH 45402

Re: Comprehensive Pre-Demolition Asbestos Inspection
Vacant Residences
2119 West Third Street
Dayton, Ohio 45417
Sierra Project Number: MCLB.002

Dear Mr. Zimmer:

On December 1, 2015, Mr. Todd Taylor and Mr. Chris Kuettner (Ohio Department of Health Certified Asbestos Hazard Evaluation Specialists #ES32139, #ES33689 respectively) of Sierra Environmental Group, Inc. (Sierra) visited the vacant residences located at 2119 West Third Street in Dayton, Ohio. The purpose of this visit was to conduct a comprehensive asbestos inspection of these specified residences scheduled for demolition. This inspection process includes a visual inspection, as well as, the collection and analyses of samples from suspect asbestos-containing materials.

During the survey, the samples were collected utilizing sampling methods outlined in current EPA Guidance Documents. Each sample was collected and placed in a clean, sealable container and labeled with a unique sample identification number. Pertinent information was recorded on a Bulk Sample Log Sheet, including sample identification number, date of inspection, name of inspector, building name, a brief description and location of the sample, and the type of material sampled (e.g., thermal insulation, fireproofing, acoustical plaster). The samples were submitted to an analytical laboratory and analyzed for asbestos content by polarized-light microscopy (PLM) and dispersion staining (Method Reference: EPA-600/R-93/116). This analytical method, which the EPA currently recommends for the determination of asbestos in bulk samples of suspect materials, can be used for qualitative identification of six morphologically different types of asbestos fibers: chrysotile, amosite, crocidolite, anthophyllite, tremolite, and actinolite asbestos.

The method specifies that the asbestos content in a bulk sample shall be estimated and reported as a finite percentage (rounded to the nearest percentage) within the range of 0 to 100. The result of the bulk sample analysis is reported in a standard written laboratory report. This report includes the client's name, the project number, the laboratory identification number, the sample number assigned to the bulk sample upon receipt at the laboratory, and the field number assigned to the bulk sample upon collection on site. If the bulk sample contains more than one distinct layer of material, each layer is analyzed separately. The composition of the bulk sample is reported in percentages of asbestos (i.e., chrysotile, amosite, or other) and non-asbestos (i.e., cellulose, fiberglass, or other) components. The results of the sample analyses can be found on the laboratory report enclosed and Table 1.

Sierra collected samples from wall and ceiling systems, roofing materials, ceiling tiles, window glaze, flooring materials and duct insulation. One (1) asbestos-containing material was identified within the residences scheduled for demolition (Table -2 Asbestos Inventory). The cost to remove the Regulated Asbestos-Containing Materials (RACM) from this site prior to demolition would be \$3,400.00. These costs have been estimated and are based on local wage rates and do not include prevailing wage rates. These costs do not include specifications, permits, contractor oversight or third party monitoring.

Sierra made every effort to locate suspect asbestos-containing materials that may be concealed; however, suspect asbestos-containing materials which may be located behind hard plaster walls or ceilings, hard walled chases, under flooring or sub-flooring, under building contents, etc., were not assessed or quantified. If through demolition suspect materials are discovered

that were not sampled during the initial site visit; Sierra should be notified to document any additional samples that may be required and handled accordingly.

This report is prepared to assist the Montgomery County Land Reutilization Corporation, City of Dayton, construction managers and asbestos abatement contractors in locating asbestos-containing materials. This report is not intended as a bidding document or project specifications.

Enclosed are the following Sierra documents: 1) Table 1-Bulk Sample Data Summary; 2) Table 2-Asbestos Inventory; 3) Table 3-Cost Estimate; 4) Laboratory Report; 5) Floor Plans; 6) Site Photographs and 7) Inspector's Certification. If we can be of further assistance on this or any other project, do not hesitate to call us at (513) 542-5323.

Sincerely,

SIERRA ENVIRONMENTAL GROUP, INC.



Todd Taylor
Operations Manager

Attachments



TABLE 1: BULK SAMPLE DATA SUMMARY

SAMPLE DESCRIPTION (Material Type)	SAMPLE LOCATION	HOMO AREA #	SAMPLE I.D. NO.	ASBESTOS CONTENT	FRIABLE/ NONFRIABLE
The following samples were collected from the vacant residences located at 2119 West Third Street, Dayton, Ohio.					
Skim coat of hard wall plaster (Surfacing, <5,000 sf)	Living room, 1st floor	1	1-1	None Detected	Nonfriable
Skim coat of hard ceiling plaster (Surfacing, <5,000 sf)	Living room, 1st floor	1	1-2	None Detected	Nonfriable
Skim coat of hard wall plaster (Surfacing, <5,000 sf)	Kitchen, 1st floor	1	1-3	None Detected	Nonfriable
Skim coat of hard ceiling plaster (Surfacing, <5,000 sf)	Kitchen, 1st floor	1	1-4	None Detected	Nonfriable
Skim coat of hard wall plaster (Surfacing, <5,000 sf)	Front left bedroom, 2nd floor	1	1-5	None Detected	Nonfriable
Skim coat of hard ceiling plaster (Surfacing, <5,000 sf)	Front left bedroom, 2nd floor	1	1-6	None Detected	Nonfriable
Skim coat of hard wall plaster (Surfacing, <5,000 sf)	Attic stairwell	1	1-7	None Detected	Nonfriable
Brown coat of hard wall plaster (Surfacing, <5,000 sf)	Living room, 1st floor	2	2-1	None Detected	Nonfriable
Brown coat of hard ceiling plaster (Surfacing, <5,000 sf)	Living room, 1st floor	2	2-2	None Detected	Nonfriable
Brown coat of hard wall plaster (Surfacing, <5,000 sf)	Kitchen, 1st floor	2	2-3	None Detected	Nonfriable
Brown coat of hard ceiling plaster (Surfacing, <5,000 sf)	Kitchen, 1st floor	2	2-4	None Detected	Nonfriable
Brown coat of hard wall plaster (Surfacing, <5,000 sf)	Front left bedroom, 2nd floor	2	2-5	None Detected	Nonfriable
Brown coat of hard ceiling plaster (Surfacing, <5,000 sf)	Front left bedroom, 2nd floor	2	2-6	None Detected	Nonfriable
Brown coat of hard wall plaster (Surfacing, <5,000 sf)	Attic stairwell	2	2-7	None Detected	Nonfriable
Duct insulation (Thermal System Insulation)	Dining room, 1st floor	3	3-1	55% Chrysotile	Nonfriable
2'x4' Suspended ceiling tile with holes and gouges (Miscellaneous)	Side room, 1st floor	4	4-1	None Detected	Nonfriable

TABLE 1: BULK SAMPLE DATA SUMMARY

SAMPLE DESCRIPTION (Material Type)	SAMPLE LOCATION	HOMO AREA #	SAMPLE I.D. NO.	ASBESTOS CONTENT	FRIABLE/ NONFRIABLE
2'x4' Suspended ceiling tile with holes and gouges (Miscellaneous)	Side room, 1st floor	4	4-2	None Detected	Nonfriable
Drywall (Miscellaneous)	Kitchen, 1st floor	5	5-1	None Detected	Nonfriable
Drywall (Miscellaneous)	Kitchen, 1st floor	5	5-2	None Detected	Nonfriable
Joint compound (Miscellaneous)	Kitchen, 1st floor	6	6-1	None Detected	Nonfriable
Joint compound (Miscellaneous)	Kitchen, 1st floor	6	6-2	None Detected	Nonfriable
Window glaze (Miscellaneous)	Exterior	7	7-1	None Detected	Friable
Window glaze (Miscellaneous)	Exterior	7	7-2	None Detected	Friable
Textured wall (Surfacing, <1,000 sf)	Hallway, 1st floor	8	8-1	None Detected	Nonfriable
Textured ceiling (Surfacing, <1,000 sf)	Bathroom, 1st floor	8	8-2	None Detected	Nonfriable
Textured ceiling (Surfacing, <1,000 sf)	Bathroom, 1st floor	8	8-3	None Detected	Nonfriable
12"x12" Tan sticky back floor tile (Miscellaneous)	Bathroom, 2nd floor	9	9-1	None Detected	Nonfriable
12"x12" Tan sticky back floor tile (Miscellaneous)	Bathroom, 2nd floor	9	9-2	None Detected	Nonfriable
Black asphalt roof shingle (Miscellaneous)	Exterior	10	10-1	None Detected	Nonfriable
Black asphalt roof shingle (Miscellaneous)	Exterior	10	10-2	None Detected	Nonfriable
Tan linoleum (Miscellaneous)	Stairwell landing	11	11-1	None Detected	Nonfriable
Tan linoleum (Miscellaneous)	Stairwell landing	11	11-2	None Detected	Nonfriable

TABLE 2 - ASBESTOS INVENTORY

Location	Type ACM	Material Description	Amt. of Material (approx.)
The following asbestos-containing materials are located in the vacant residences located at 2119 West Third Street, Dayton, Ohio.			
Basement	RACM	Duct insulation	45 sf
Basement to 2nd floor	RACM	Duct insulation (concealed behind hard wall and ceiling plaster)	100 sf

TABLE 3 - COST ESTIMATE

Location	Type ACM	Material Description	Cost for abatement (approx.)
The following asbestos-containing materials are located in the vacant residences located at 2119 West Third Street, Dayton, Ohio.			
Basement	RACM	Duct insulation	\$900.00
Basement to 2nd floor	RACM	Duct insulation (concealed behind hard wall)	\$2,500.00



Environmental Hazards Services, L.L.C.
 7469 Whitepine Rd
 Richmond, VA 23237
 Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 15-12-00144

Client: Sierra Environment Group Inc.
 1041 Straight Street
 Cincinnati, OH 45214

Received Date: 12/02/2015
Analyzed Date: 12/04/2015
Reported Date: 12/07/2015

Project/Test Address: MCLB.002; 2119 W. Third St.

Client Number:
 36-6195

Laboratory Results

Fax Number:
 513-542-6653

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
15-12-00144-001	1-1		White Granular; Homogeneous	NAD	100% Non-Fibrous
15-12-00144-002	1-2		White Granular; Homogeneous	NAD	100% Non-Fibrous
15-12-00144-003	1-3		White Granular; Homogeneous	NAD	100% Non-Fibrous
15-12-00144-004	1-4		White Granular; Homogeneous	NAD	100% Non-Fibrous
15-12-00144-005	1-5		White Granular; Homogeneous	NAD	100% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 36-6195
Project/Test Address: MCLB.002; 2119 W. Third St.

Report Number: 15-12-00144

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
15-12-00144-006	1-6		White Granular; Homogeneous	NAD	100% Non-Fibrous
15-12-00144-007	1-7		White Granular; Homogeneous	NAD	100% Non-Fibrous
15-12-00144-008	2-1		Gray Granular; Homogeneous	NAD	2% Hair 98% Non-Fibrous
15-12-00144-009	2-2		Gray Granular; Homogeneous	NAD	2% Hair 98% Non-Fibrous
15-12-00144-010	2-3		Gray Granular; Homogeneous	NAD	2% Hair 98% Non-Fibrous
15-12-00144-011	2-4		Gray Granular; Homogeneous	NAD	2% Hair 98% Non-Fibrous
15-12-00144-012	2-5		Gray Granular; Homogeneous	NAD	2% Hair 98% Non-Fibrous
15-12-00144-013	2-6		Gray Granular; Homogeneous	NAD	2% Hair 98% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 36-6195
 Project/Test Address: MCLB.002; 2119 W. Third St.

Report Number: 15-12-00144

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
15-12-00144-014	2-7		Gray Granular; Homogeneous	NAD	2% Hair 98% Non-Fibrous
15-12-00144-015	3-1		Gray Fibrous; Homogeneous	55% Chrysotile	20% Cellulose 25% Non-Fibrous
Total Asbestos: 55%					
15-12-00144-016	4-1		White Paint-Like; Gray Fibrous; Inhomogeneous	NAD	35% Cellulose 45% Fibrous Glass 20% Non-Fibrous
15-12-00144-017	4-2		White Paint-Like; Gray Fibrous; Inhomogeneous	NAD	35% Cellulose 45% Fibrous Glass 20% Non-Fibrous
15-12-00144-018	5-1		White Powdery; Brown Fibrous; Inhomogeneous	NAD	18% Cellulose 82% Non-Fibrous
15-12-00144-019	5-2		White Powdery; Homogeneous	NAD	12% Cellulose 88% Non-Fibrous
15-12-00144-020	6-1		White Granular; Homogeneous	NAD	100% Non-Fibrous
15-12-00144-021	6-2		White Granular; Homogeneous	NAD	100% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 36-6195
Project/Test Address: MCLB.002; 2119 W. Third St.

Report Number: 15-12-00144

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
15-12-00144-022	7-1		White Brittle; Homogeneous	NAD	100% Non-Fibrous
15-12-00144-023	7-2		White Brittle; Homogeneous	NAD	100% Non-Fibrous
15-12-00144-024	8-1		White Paint-Like; Granular; Inhomogeneous	NAD	100% Non-Fibrous
15-12-00144-025	8-2		White Paint-Like; Granular; Inhomogeneous	NAD	100% Non-Fibrous
15-12-00144-026	8-3		White Paint-Like; Granular; Inhomogeneous	NAD	100% Non-Fibrous
15-12-00144-027	9-1		White Vinyl; Homogeneous	NAD	100% Non-Fibrous
15-12-00144-028	9-2		White Vinyl; Homogeneous	NAD	100% Non-Fibrous
15-12-00144-029	10-1		Gray/Black Aggregate; Black Tar-Like; Inhomogeneous	NAD	15% Fibrous Glass 85% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 36-6195
Project/Test Address: MCLB.002; 2119 W. Third St.

Report Number: 15-12-00144

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
15-12-00144-030	10-2		Gray/Black Aggregate; Black Tar-Like; Inhomogeneous	NAD	15% Fibrous Glass 85% Non-Fibrous
15-12-00144-031	11-1		Tan Vinyl; Black Black Tar-Like; Fibrous; Inhomogeneous	NAD	55% Cellulose 3% Hair 42% Non-Fibrous
15-12-00144-032	11-2		Tan Vinyl; Black Black Tar-Like; Fibrous; Inhomogeneous	NAD	55% Cellulose 3% Hair 42% Non-Fibrous


Environmental Hazards Services, L.L.C

Client Number: 36-6195
Project/Test Address: MCLB.002; 2119 W. Third St.

Report Number: 15-12-00144

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
-------------------	----------------------	------------	-----------------------	----------	-----------------

QC Sample: 75-M22009-3
QC Blank: SRM 1866 Fiberglass
Reporting Limit: 1% Asbestos
Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020
Analyst: Sami Hosn

Reviewed By Authorized Signatory: 

 Howard Varner
 General Manager

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0 VELAP 460172. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND:	NAD = no asbestos detected
---------	----------------------------



Analyst Signature Page

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Client: Sierra Environment Group Inc.
1041 Straight Street
Cincinnati, OH 45214

Client Number: 36-6195

Project/Test Address: MCLB.002; 2119 W. Third St.

Report Number: 15-12-00144

Received Date: 12/02/2015

Analyzed Date: 12/04/2015

Reported Date: 12/07/2015

Analyst(s)

A handwritten signature in black ink, appearing to read "Sami Hosn". The signature is written in a cursive style with some loops and flourishes.

Sami Hosn



Environmental Hazards Services, LLC

www.leadlab.com 7469 Whitepine Rd
 (800)347-4010 Richmond, VA 23237
 (804)275-4907 (fax)

32 PLM

Asbestos Chain-of-Custody

15-12-00144



Due Date:
 12/07/2015
 (Monday)
 AE M Inv

S

Company Name: Sierra Environmental Group, Inc. Address: 1041 Straight Street City/State/Zip: Cincinnati, OH 45214

Phone: (513) 542-5323 Fax: () E-mail: Acct. Number: 36-6195

Project Name / Testing Address: MCLB. 002-2119 W. Third St City/State (Required): Purchase Order Number:

Collected by: T. T. [Signature]

Turn Around Times : **If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.**

1 - Day 2 - Day 3 - Day Same Day (Must Call Ahead) Weekend (Must Call Ahead)

No.	Client Sample ID	Date Collected	ASBESTOS						AIR			Volume (Total Liters)	COMMENTS	
			PLM Point Count 400	PLM Point Count 1000	PLM NY Protocol	PCM	TEM Certified (Bulk)	TEM AHERA (Air)	Time On	Time Off	Flow Rate (L/min)			Total Time (minutes)
1	1-1	12-1-15	-	-	-	-	-	-	-	-	-	-	-	Stop if positive STP
2	1-2	↓	-	-	-	-	-	-	-	-	-	-	-	STP
3	1-3		-	-	-	-	-	-	-	-	-	-	-	↓
4	1-4		-	-	-	-	-	-	-	-	-	-	-	↓
5	1-5		-	-	-	-	-	-	-	-	-	-	-	↓
6	1-6		-	-	-	-	-	-	-	-	-	-	-	↓
7	1-7		-	-	-	-	-	-	-	-	-	-	-	↓
8	2-1		-	-	-	-	-	-	-	-	-	-	-	↓
9	2-2		-	-	-	-	-	-	-	-	-	-	-	↓
10	2-3		-	-	-	-	-	-	-	-	-	-	-	↓

Released by: T. T. [Signature] Date/Time: 12/2/15
 Received by: T. T. [Signature] Date/Time: 12/2/15



Environmental Hazards Services, LLC

www.leadlab.com

7469 Whitepine Rd
Richmond, VA 23237

(800)347-4010
(804)275-4907 (fax)

Asbestos Chain-of-Custody

~ For Lab Use Only ~

144

Company Name: Sierra Environmental Group, Inc. Address: 1041 Straight Street

City/State/Zip: Cincinnati, OH 45214

Phone: (513) 542-5323

Fax: ()

E-mail:

Acct. Number: 36-6195

Project Name / Testing Address: T-TAT

MCLB, 002-2119 w. Third St

City/State (Required):

Collected by: T-TAT

Purchase Order Number:

Turn Around Times:

If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.

1 - Day

2 - Day

3 - Day

Same Day (Must Call Ahead)

Weekend (Must Call Ahead)

No.	Client Sample ID	Date Collected	ASBESTOS						AIR			Volume (Total Liters)	COMMENTS	
			PLM	PLM Point Count 400	PLM Point Count 1000	PLM NY Protocol	PCM	TEM Certified (Bulk)	TEMAHERA (Air)	Time On	Time Off			Flow Rate (L/min)
1	2-1	12-1-15	-											
2	2-5	→	-											
3	2-6													
4	2-7													
5	3-1													
6	4-1													STP
7	4-2													↓ STP
8	5-1													↓ STP
9	5-2													↓ STP
10	6-1													↓ STP

Released by: T. TAT

Received by: T. TAT

Signature: [Signature]

Signature: [Signature]

[Signature]

Date/Time:

Date/Time: 12/1/15



Asbestos Chain-of-Custody

Environmental Hazards Services, LLC

www.leadlab.com 7469 Whitepine Rd
 (800)347-4010 Richmond, VA 23237
 (804)275-4907 (fax)

1000

~ For Lab Use Only ~

Company Name: Sierra Environmental Group, Inc. Address: 1041 Straight Street City/State/Zip: Cincinnati, OH 45214

Phone: (513) 542-5323 Fax: () E-mail: Acct. Number: 36-6195

Project Name / Testing Address: MCLB, 002-2119 W. Third St City/State (Required):

Collected by: T. TAYLOR Purchase Order Number:

Turn Around Times: **If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.**
 1 - Day 2 - Day 3 - Day
 Same Day (Must Call Ahead) Weekend (Must Call Ahead)

No.	Client Sample ID	Date Collected	ASBESTOS						AIR			COMMENTS		
			PLM	PLM Point Count 400	PLM Point Count 1000	PLM NY Protocol	PCM	TEM Certified (Bulk)	TEM AHERA (Air)	Time On	Time Off		Flow Rate (L/min)	Total Time (minutes)
1	6-2	12-1-15	-											→ STOP
2	7-1	}	-											→ STOP
3	7-2													→ STOP
4	8-1													→ STOP
5	8-2													→ STOP
6	8-3													→ STOP
7	9-1													→ STOP
8	9-2													→ STOP
9	10-1													→ STOP
10	10-2													→ STOP
Released by: T. TAYLOR			Signature:		Date/Time: 12-1-15		Signature:		Date/Time: 12-1-15					
Received by:		Signature:		Date/Time: 12-1-15		Signature:		Date/Time: 12-1-15						



Environmental Hazards Services, LLC

www.leadlab.com 7469 Whitepine Rd
 (800)347-4010 Richmond, VA 23237
 (804)275-4907 (fax)

Asbestos Chain-of-Custody

144

~ For Lab Use Only ~

Company Name: Sierra Environmental Group, Inc. Address: 1041 Straight Street City/State/Zip: Cincinnati, OH 45214

Phone: (513) 542-5323 Fax: () E-mail: Acct. Number: 36-6195

Project Name / Testing Address: MCLB, 002-2119 W. Third St. City/State (Required):

Collected by: T. Taly Purchase Order Number:

Turn Around Times : If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.

1 - Day 2 - Day 3 - Day Same Day (Must Call Ahead) Weekend (Must Call Ahead)


No.	Client Sample ID	Date Collected	ASBESTOS						AIR			Volume (Total Liters)	COMMENTS	
			PLM	PLM Point Count 400	PLM Point Count 1000	PLM NY Protocol	PCM	TEM Clarified (Bulk)	TEM AHERA (Air)	Time On	Time Off			Flow Rate (L/min)
1	111	12-1-15	-											STP
2	112	↓	-											↓
3														
4														
5														
6														
7														
8														
9														
10														

Released by: T. Taly Signature: [Signature]


Signature: [Signature]

Date/Time: 12-1-15


2119 WEST 3RD STREET
BASEMENT



2119 WEST 3RD STREET
FIRST FLOOR



2119 WEST 3RD STREET
SECOND FLOOR




2119 WEST 3RD STREET
THIRD FLOOR







2119 West 3rd Street



Hard wall and ceiling plaster



Duct insulation




2'x4' Suspended ceiling tile with holes and gouges



Drywall and associated joint compound




Window glaze




Textured wall and ceiling



12" Tan sticky back floor tile



Black asphalt roof shingle



Tan linoleum

OHIO DEPARTMENT OF HEALTH

614/466-3513

www.odh.ohio.gov

Richard Ronger/ Director of Health

May 12, 2015

Todd E. Taylor
Sierra Environmental Group, Inc.
1041 Straight Street
Cincinnati OH 45214

RE: Asbestos Hazard Evaluation Specialist
Certification Number: ES32139
Expiration Date: 05/19/2016

Dear Todd E Taylor:

This letter and enclosed certification card approves your request to be certified as an Asbestos Hazard Evaluation Specialist. You must present your card upon request at any project site while performing duties. Copies of cards are not acceptable as proof of certification.

This certification may be revoked by the Director of Health for violation of any of the requirements of 3701-34 of the Ohio Administrative Code.

If you have any questions, please call Kathy Butcher, Licensure Specialist, at 614-644-0226.

Sincerely,


Bill Robbins, Section Chief
Bureau of Licensure Operations
Office of Health Assurance and Licensing

State of Ohio
Department of Health
Asbestos Program

Asbestos Hazard Evaluation Specialist


Todd E Taylor
Sierra Environmental Group, Inc.
1041 Straight Street
Cincinnati OH 45214

Certification Number: **ES32139** Expiration Date: **05/19/2016**

DOB: 07/23/1967

This certification is issued pursuant to Chapter 3710 of the Ohio Administrative Code. It is not valid if altered.

OHIO DEPARTMENT OF HEALTH

August 26, 2015

Christopher P Kuettner
Sierra Environmental Group, Inc.
1041 Straight Street
Cincinnati OH 45214

RE: Asbestos Hazard Evaluation Specialist
Certification Number: ES33689
Expiration Date: 10/14/2016

Dear Christopher P Kuettner:

This letter and enclosed certification card approves your request to be certified as an Asbestos Hazard Evaluation Specialist. You must present your card upon request at any project site while performing duties. Copies of cards are not acceptable as proof of certification.

This certification may be revoked by the Director of Health for violation of any of the requirements of 3701-34 of the Ohio Administrative Code.

If you have any questions, please call Kathy Butcher, Licensure Specialist, at 614-644-0226.

Sincerely,



Bill Robbins, Section Chief
Bureau of Licensure Operations
Office of Health Assurance and Licensing

State of Ohio
Department of Health
Asbestos Program

Asbestos Hazard Evaluation Specialist



Christopher P Kuettner
Sierra Environmental Group, Inc.
1041 Straight Street
Cincinnati OH 45214

DOB: 11/17/1956 Certification Number: **ES33689** Expiration Date: **10/14/2016**

This certification is issued pursuant to Chapter 3701 of the Revised Code and 3701-04 of the Ohio Administrative Code. Certification Card is not valid if altered.